













HENRY 5K CLASSIC RF DECK - MARK II






OPERATING CONTROLS - 3K CLASSIC X Mark II and 5K CLASSIC

1. Plate Current Meter.
2. Multimeter.
3. Multimeter and Relay Control Switches.
4. STANDBY Light.
5. POWER Light.
6. BAND Switch.
7. TUNE Control.
8. LOAD Control.
9. SSB/CW Switch.
10. OFF/ON Power Switch-Circuit Breaker.
11. AC Fuse.
12. AC Fuse.
13. Adjustable Feet.
14. RF Output Connector.
15. Cathode Fuse.
16. RF Input Connector.
17. ALC Connector.
18. RELAY Connector.
19. ALC Adjust Potentiometer.
20. Ground Stud.
21. Serial Number Tag.
22. Air Flow Filter.
23. AC Power Connector.



3K&5K CLASSIC POWER SUPPLY-LOWER DECK

7/30/86



DIM	INCHES			MILLIMETERS		
	MIN	MAX	REF	MIN	MAX	REF
A		5.400			137.16	
B			2.750			67.4
C			2.500			63.5
D			.312			7.65
E			1.500			36.75
F			3.375			82.7
G	.700	.800		17.15	19.6	
H			.937			22.95
K			30°			30°
L	.185	.191		4.53	4.68	
M			1.250			30.63
N			2.875			70.44

NOTES:

1. REF DIMENSIONS ARE FOR INFO ONLY & ARE NOT REQUIRED FOR INSPECTION PURPOSES.